COMPONENT NAME TRANSMISSION

PART NUMBER 205-540-010-101

SERIAL NUMBER ABT-01138

PAGE _____ OF _____

HISTORICAL SERVICE RECORD

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT FOR ANY REASON, IT IS MANDATORY THAT A VALID **HISTORICAL SERVICE RECORD** ACCOMPANY COMPONENT.

INSTALLATION DATA						NEXT SCHEDULED	REMOVAL DATA – SUBJECT TO SUBCOMPONENTS				
DATE	INSTALLED ON AIRCRAFT SERIAL NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS RIN	COMP. HRS / RIN SINCE NEW COMP. HRS RIN	COMP. HRS / RIN SINCE O/H COMP. HRS RIN	INSP ☐ O/H ☐ RET ☐ COMP. HRS RIN	DATE	REMOVED AT A/C HRS RIN	COMP. HRS / RIN SINCE NEW COMP. HRS RIN	COMP. HRS / RIN SINCE O/H COMP. HRS RIN	REASON FOR REMOVAL
05/04	[illegible]	[illegible]	[illegible]	7902:20	0.0		12/10	8469:40	9463:25	1561:05	Repair/Crack above input Quill
[illegible]	[illegible]	[illegible]	[illegible]	9463:25	1561:05		10/3/16	8974.6	99683	2066.1	DUE OVERHAUL.

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

COMPONENT TOTAL TIME/RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE	CERT. NO.	DATE
7902:20	This assembly overhauled, and conditional inspection carried out under Heli Technology W/O **031617**. Backlash as follows: Input 0.009", No.2 Hyd 0.009", No.1 Hyd 0.020", & T/R 0.005". Bulletins ASB's 205-92-47, 205-92-50a, 205-93-54, 205-93-58A, 205-95-62A, 205-01-82, 205-01-83 c/w. AD's CF94-07, 89-08-05, 93-17-12, & 94-18-08 c/w. All work carried out in accordance with Bell BHT-205-CR&O-1 manual Rev.2	[signature]	HTI - 001 210 - 91	~~JAN 20 2011~~ 6 APR 2004
9463:25	The following work was carried out under Heli Technology work order **C00379**: Assembly repaired, overhauled Main Case installed. All work was carried out in accordance with BHT-205-CR&O-1 Rev.4	[signature]	HTI - 001 210 - 91	JAN 20 2011

COMPONENT NAME PLANETARY SPIDER

PART NUMBER 204-040-785-003

SERIAL NUMBER B12-11460

PAGE _____ OF _____

HISTORICAL SERVICE RECORD

NOTICE: WHEN RETURNING ANY LIMITED LIFE COMPONENT FOR ANY REASON, IT IS MANDATORY THAT A VALID **HISTORICAL SERVICE RECORD** ACCOMPANY COMPONENT.

INSTALLATION DATA						NEXT SCHEDULED INSP ☐ O/H ☐ RET ☐	REMOVAL DATA - SUBJECT TO SUBCOMPONENTS				
DATE	INSTALLED ON AIRCRAFT SERIAL NO.	BY (ACTIVITY)	INSTALLED AT A/C HRS RIN	COMP. HRS / RIN SINCE NEW COMP. HRS RIN	COMP. HRS / RIN SINCE O/H COMP. HRS RIN	COMP. HRS RIN	DATE	REMOVED AT A/C HRS RIN	COMP. HRS / RIN SINCE NEW COMP. HRS RIN	COMP. HRS / RIN SINCE O/H COMP. HRS RIN	REASON FOR REMOVAL
[illegible]	[illegible]	[illegible]	[illegible]	UNK	0.0		10/3/16	8974.6	unk.	505.1	

HISTORY OF INSPECTION, OVERHAUL, REPAIR AND APPLICATION OF TECHNICAL BULLETIN, SERVICE BULLETIN, AIRWORTHINESS DIRECTIVES, ETC.

COMPONENT TOTAL TIME/RIN	DESCRIPTION OF WORK ACCOMPLISHED	COMPLIED WITH BY SIGNATURE	CERT. NO.	DATE
UNK	THIS UNIT OVERHAULED & RE-INSTALLED ON TRANSMISSION S/N			
	ABT-01138 AT 7902:20 HRS ASSY TOTAL TIME. AD 93-17-12,			
	94-18-09 C/W. ASB 205-92-50A & 205-93-54 C/W.	[signature]	[illegible]	

3

COMPONENT NAME / PART NUMBER	SERIAL NUMBERS	ORIGINALLY PLACED IN SERVICE: DATE / COMPONENT HOURS	INSTALLATION DATA: ACCUMULATED TIME ON ASSEMBLY OR PART: SINCE NEW (HRS)	INSTALLATION DATA: ACCUMULATED TIME ON ASSEMBLY OR PART: SINCE OVERHAUL (HRS)	SCHEDULED REMOVAL: DATE / COMPONENT HOURS	REMOVAL DATA: DATE / AIRCRAFT HOURS	REMOVAL DATA: ACCUMULATED TIME ON ASSEMBLY OR PART: SINCE NEW (HRS)	REMOVAL DATA: ACCUMULATED TIME ON ASSEMBLY OR PART: SINCE OVERHAUL (HRS)
NAME: SPIDER	B12-11460	31-03-04	UNK	0.0				
NO.: 204-040-785-3		UNK						
NAME: CLUTCH	FDFS19571	31-03-04	0.0					
NO.: 205-040-250-103		UNK						
NAME:								
NO.:								
NAME:								
NO.:								
NAME:								
NO.:								
NAME:								
NO.:								
NAME:								
NO.:								
NAME:								
NO.:								
NAME:								
NO.:								
NAME:								